

Rev: 01

Date: 5/23/87

TYPE II

NAVY STANDARDS LABORATORY

SPRINGFIELD

LOCAL CALIBRATION PROCEDURE (LCP)

LCP-WJL-024

for

GUILDLINE 9923 RANGE EXTENDER

Prepared by

Unified Industries, Inc

TABLE OF CONTENTS

Section	Page
1 Introduction and Description.	1
2 Equipment Requirements.	2
3 Preliminary Operations.	4
4 Calibration Process	7
4.1 0.1 ohm and 10 ohm Standard Resistor Calibration. . .	7
4.2 Zeroing the TI.	12
4.3 TI Measurement Process.	13
4.4 10:1 Ratio Test	21
4.5 0.1 ohm and 0.01 ohm Standard Resistor Calibration. .	22
4.6 100:1 Ratio Test.	23
4.7 0.01 ohm and 0.001 ohm Standard Resistor Calibration.	24
4.8 1000:1 Ratio Test	26
Worksheets.	28
Appendix A: CALEXTENDR Program Instructions	A-1

ILLUSTRATIONS

Figure	Page
1 Resistance Bridge Controls.	6
2 Resistance Test Setup	8
3 Ratio Test Setup.	15

TABLES

Table	Page
1 Calibration Description	1

SECTION 1

INTRODUCTION AND DESCRIPTION

1.1 This procedure describes the calibration of the Guildline Model 9923 Range Extender. The instrument being calibrated is referred to herein as the TI (Test Instrument).

1.2 This procedure includes tests of essential performance parameters only. Any malfunctions noticed during calibration, whether specifically tested for or not, should be corrected.

Table 1. Calibration Description

TI Characteristics	Performance Specifications	Test Method
Transformation Ratio	Range: 10:1 Uncertainty: 0.5 ppm Range: 100:1 Uncertainty: 0.5 ppm Range: 1000:1 Uncertainty: 1 ppm	Comparison to an established standard resistance ratio measured by a resistance measurement system.

SECTION 2
EQUIPMENT REQUIREMENTS

NOTE

Minimum use specifications are the principal parameters required for performance of the calibration. All applicable equipment must bear evidence of current calibration.

Item	Minimum Use Specifications	Calibration Equipment
2.1 Direct Current Comparator Resistance Bridge	No substitute	Guildline 9975
2.2 Range Plug	No substitute	Guildline 99753
2.3 Reversing Switch	No substitute	Guildline 9606
2.4 DC Power Supply #1	Range: 0 to 2 Amp Uncertainty: $\pm 0.2\%$ Stability: $<0.03\%$ of output	John Fluke 382A
2.5 DC Power Supply #2	Range: 0 to 10 Amp Uncertainty: $\pm 2\%$ of fs Stability: $<0.03\%$ of output plus 20 mA	Hewlett Packard 6260B
2.6 Primary Standard Resistor (3 required)	Range: 1 ohm Uncertainty: ± 0.08 ppm (Calibrated by NBS and monitored by MCP-WJL-002. Limited to R1, R2 and R3 listed within the MCP.)	Leeds & Northrup 4210
2.7 Standard Resistor	Range: 0.001 ohm Uncertainty: ± 0.4 ppm (Established during procedure and IAW MCP-WJL-002)	Leeds & Northrup 4223

Item	Minimum Use Specifications	Calibration Equipment
2.8 Standard Resistor	Range: 0.01 ohm Uncertainty: ± 0.2 ppm (Established during procedure and IAW MCP-WJL-002)	Leeds & Northrup 4222
2.9 Standard Resistor	Range: 0.1 ohm Uncertainty: ± 0.2 ppm (Established during procedure and IAW MCP-WJL-002)	Leeds & Northrup 4221
2.10 Standard Resistor	Range: 10 ohm Uncertainty: ± 0.2 ppm (Established during procedure and IAW MCP-WJL-002)	Leeds & Northrup 4025
2.11 Current Shunt	Range: 15 Amps/0.1 ohm Uncertainty: $\pm 0.1\%$	Leeds & Northrup 4360
2.12 Digital Multi-meter (DMM)	Range: 0 to 2 Vdc Uncertainty: $\pm 0.1\%$	Datron 1072
2.13 Oil Bath	Range: 25°C Uncertainty: $\pm 0.05^\circ\text{C}$	Guildline 9730C
2.14 Shielded Copper Wire	Type: 22 AWG, twisted pair solid conductor	Guildline Type SCW or equivalent
2.15 Stranded Copper Wire	Must be capable of handling applied currents of up to 10 Amps (400cm/Amp) 1 Amp - 20 AWG 10 Amp - 14 AWG	Local Supply
2.16 Computer	No Substitute	Hewlett-Packard HP-9816
2.17 Program	No Substitute	CALEXTENDR

SECTION 3

PRELIMINARY OPERATIONS

3.1 Ensure that all power switches are set to off or standby. Set all auxiliary equipment controls as necessary to avoid damage to the equipment and so that dangerous voltage will not be present on output terminals when the power switches are turned on.

3.2 Connect the auxiliary equipment to the appropriate power sources.

3.3 Turn the Resistance Bridge (Item 2.1) on and allow for a sufficient warm-up time. (Lab policy requires unit to be on at all times).

CAUTION

IF THE OSC LIGHT IS EXTINGUISHED AT ANY TIME WHEN THE POWER IS ON, TURN THE POWER OFF IMMEDIATELY AND TAKE CORRECTIVE ACTION AS NECESSARY.

3.4 Ensure the Resistance Bridge pre-operational checkout and setup procedure has been performed in the last 30 days in accordance with LCP-WJL-001 Appendix A.

3.5 Place the Standard Resistors (Item 2.6 through 2.10) in the Oil Bath (Item 2.13) and allow sixteen hours to attain temperature stability.

3.6 Set the Resistance Bridge controls as follows (see Figure 1 for switch/control locations):.

Note

Ensure that Standard Resistors remain in the Oil Bath throughout the procedure to ensure the accuracy and stability of the resistance measurements.

Side Panel Controls

PCA/OUT switch to	OUT
REV/RATE switch to	8
Rs Ω switch to	1
MAN/AUTO switch to	MAN
INT/EXT switch to	INT
Rx/Rs dials to	10.00000-1

Front Panel Controls

CURRENT IxmA switch to	0
X1 X $\sqrt{2}$ switch to	X1
GALVANOMETER SENSITIVITY switch to	X1
GALVANOMETER D1/D2 switch to	D1
TIME CONSTANT switch to	1





Figure 1. 9975 Resistance Bridge Controls

SECTION 4

CALIBRATION PROCESS

NOTE

Unless otherwise specified, verify the results of each test and take corrective action whenever the test requirement is not met, before proceeding.

4.1 0.1 OHM AND 10 OHM STANDARD RESISTOR CALIBRATION

NOTE

The 0.1 ohm and 10 ohm Standard Resistors (Item 2.9 and 2.10) are calibrated against the Primary Standard Resistor(s) (Item 2.6) to establish an uncertainty of 0.2 ppm. Their values in conjunction with the Primary Standard Resistors will provide the reference ratios required to calibrate the TI 10:1 RATIO range.

4.1.2 Insert the $R_{s<1k/R_{s>10k}}$ Range Plug (side panel) with the $R_{s<1k}$ side facing up.

4.1.3 Connect the equipment as shown in Figure 2, using the 0.1 ohm Standard Resistor as R_s , and the first (of three) Primary Standard Resistors as R_x . Record the 0.1 ohm Standard Resistor Serial Number on Worksheet no. 1.

NOTE

The Primary Standard Resistors must be used in the MCP-WJL-002 data base sequence to ensure valid cross references to the data base:

R1 - READING 1
R2 - READING 2
R3 - READING 3

Note

Ensure that all connections are secure to avoid possible errant thermal resistance.




Figure 2. Resistance Test Setup

4.1.4 Adjust the 9460B Photocell Amplifier (part of Resistance Bridge) ZERO control for a null indication on the GALVANOMETER meter.

4.1.5 Set the MAN/AUTO switch (side panel) to AUTO.

NOTE

Automatic current reversing to be used as a convenience. For higher accuracy (particularly at low resistance values) a slower rate is required, either use a slower automatic rate (REV/RATE switch, side panel) or use manual switching (CURRENT REVERSING switch, front panel).

4.1.6 Set the PCA/OUT switch to PCA.

4.1.7 Set the GALVANOMETER D1/D2 switch to D2 and adjust the REC/ZERO control (side panel) for a null indication on the GALVANOMETER meter.

4.1.8 Set the GALVANOMETER D1/D2 switch to D1.

4.1.9 Set the CURRENT IxmA switch to 10 (mA)

NOTE

The above current level was selected to be large enough to minimize circuit noise effects while avoiding producing excessive self heating effects. If desired, self heating effects may be checked by measuring resistance at different current levels, which can be accomplished by setting the X1 $X\sqrt{2}$ switch to $X\sqrt{2}$ for the second measurement and subtracting the difference between the X1 and $X\sqrt{2}$ measurements to determine if the effects are present.

4.1.10 Adjust the HIGH TRACK control until no deflection is noted on the AMPERE TURN BALANCE meter upon current reversal.

4.1.11 Adjust the COMP BAL control (side panel) for a zero indication on the AMPERE TURN BALANCE meter, if necessary.

4.1.12 Adjust the GALV BALANCE control (front panel) to where the GALVANOMETER meter deflects equally on each side of center scale upon current reversal to compensate for thermal emf's.

4.1.13 Adjust the Rx/Rs dials for a balance indication on the GALVANOMETER meter.

NOTE

Balance is attained when the GALVANOMETER meter indication does not deflect upon current reversal.

4.1.14 Increase the GALVANOMETER SENSITIVITY by one (i.e. X1 to X2).

4.1.15 Readjust the GALV BALANCE control for thermal emf's, if necessary.

4.1.16 Readjust the Rx/Rs dials for a balance indication on the GALVANOMETER meter.

4.1.17 Repeat steps 4.1.14 through 4.1.16 for higher settings of the GALVANOMETER SENSITIVITY switch up to the setting which yields the required measuring sensitivity.

NOTE

The required measuring sensitivity is attained when the least significant Rx/Rs dial, which equals the Standard Resistor's required resolution (8th place), affects the balance indication on the GALVANOMETER meter.

4.1.18 Adjust the TRANSIENT SUPPRESSION control to minimize the transient "kick" on the GALVANOMETER meter.

4.1.19 Set the GALVANOMETER D1/D2 switch to D2.

4.1.20 Readjust the Rx/Rs dials for a final balance, using the GALVANOMETER meter as a null detector.

NOTE

Final balance is achieved when GALVANOMETER meter indication stops drifting.

NOTE

If the above balance was carried out in the automatic current reversing mode with the REV/RATE switch set to 8, it is recommended that balancing be repeated at a slower reversing rate (16) or use manual switching, unless previous experience proves otherwise.

NOTE

When using manual current reversing allow enough time for the GALVANOMETER meter indication to settle down before reversing current.

4.1.21 Record the Rx/Rs dials indication as READING 1 on Worksheet no. 1.

4.1.22 Set the Resistance Bridge controls as follows:

Front Panel Controls

GALVANOMETER SENSITIVITY switch to	X1
GALVANOMETER D1/D2 switch to	D1
CURRENT IxmA switch to	0
Rx/Rs dials to	10.00000-1

Side Panel Controls

PCA/OUT switch to	OUT
MAN/AUTO switch to	MAN

4.1.23 Disconnect the 1 ohm Primary Standard Resistor and replace it with the next Primary Standard Resistor.

4.1.24 Repeat steps 4.1.3 through 4.1.23 with remaining Primary Standard Resistors, recording the values as READING 2 and 3 on Worksheet no. 1.

4.1.25 Repeat steps 4.1.3 through 4.1.24 with the 10 ohm Standard Resistor as R_x and the 1 ohm Primary Standard Resistor(s) as R_s . Record the results on Worksheet no. 1 under 10 ohm Standard Resistor Calibration.

4.1.26 Disconnect the test setup.

4.1.27 Enter the Standard Resistor data and measured values recorded on Worksheet no. 1 into the HP 9816 computer (Item 2.16) program CALEXTENDR (Item 2.17) for both Standard Resistors (Refer to Appendix A for instructions).

NOTE

CALEXTENDR will determine the standard deviation and mean resistance value, correct for left/right balance (determined by MCP-WJL-002) and verify the Standard Resistance value tracks its previous calibration.

4.1.28 Enter the computed Standard Resistor values and uncertainties on Worksheet no. 1.

4.2 ZEROING THE TI

4.2.1 Adjust the TI HIGH TRACK control fully CCW.

NOTE

The TI must not have any current applied to its input or output terminals when zeroing.

4.2.2 Set the TI POWER switch to ON.

CAUTION

IF THE OSC LIGHT DOES NOT COME ON IMMEDIATELY, SET THE POWER TO OFF AND TAKE CORRECTIVE ACTION AS NECESSARY.

4.2.3 Adjust the ZERO ADJ for a null indication on the NULL meter.

4.2.4 Set the TI POWER switch to OFF.

4.3 TI MEASUREMENT PROCESS

NOTE

Due to the number of times this process will be performed, this Subsection is dedicated to the process only. The subsequent Subsections will describe the parameters tested and the test configuration changes. Proceed to Subsection 4.4 and refer back when directed.

4.3.1 Set the Resistance Bridge controls as follows (see Figure 1 for switch/control locations).

Side Panel Controls

PCA/OUT switch to	OUT
REV/RATE switch to	8
Rs Ω switch to	100
MAN/AUTO switch to	MAN
INT/EXT switch to	EXT

Front Panel Controls

CURRENT IxmA switch to	0
X1 $X\sqrt{2}$ switch to	X1
GALVANOMETER SENSITIVITY switch to	X1
GALVANOMETER D1/D2 switch to	D1
TIME CONSTANT SEC switch to	1
Rx/Rs dials to	1.000000-1

4.3.2 Remove the Resistance Bridge $R_{s<1k/Rs>10k}$ Range Plug (side panel) and replace it with the 99753 Range Plug (Item 2.2).

4.3.3 Connect the equipment as shown in Figure 3, using the appropriate Standard Resistors and Power Supply as directed. Record the Standard Resistor used in the calibration Serial Numbers on the appropriate Worksheet.

NOTE

Make all connections as short as practical and ensure the Copper Wire (Item 2.15) will handle the applied current to avoid entering errant resistance values.

1 Amp - 20 AWG
10 Amp - 14 AWG

4.3.4 Connect the Shielded Wire (Item 2.14) shields to the Resistance Bridge CCT COM terminal (side panel).

4.3.5 Set the TI RATIO switch to the selected terminal connection position.

4.3.6 Set the Resistance Bridge CURRENT IxmA switch to 100.

4.3.7 Set the Resistance Bridge CURRENT REVERSING switch from A to B then B to A, and listen for an audible click(s) to ensure activation of the Reversing Switch (Item 2.3).

4.3.8 Adjust the TI's HIGH TRACK control fully CW.

4.3.9 Set the TI's ON/OFF switch to ON.




Figure 3. Ratio Test Setup

CAUTION

DO NOT ALLOW THE DC POWER SUPPLY (ITEM 2.4/2.5) TO BE ON WHEN THE TI IS OFF. FAILURE TO OBSERVE WILL CAUSE THE TI'S TRANSFORMER TO BECOME MAGNETIZED.

CAUTION

IF AT ANY TIME THE TI'S OSC LIGHT IS EXTINGUISHED, TURN THE DC POWER SUPPLY AND TI POWER TO OFF IMMEDIATELY. THIS CONDITION INDICATES THE OSCILLATOR HAS STOPPED DUE TO OVERLOAD. ALLOW 30 SECONDS FOR THE OSCILLATOR TO RESET, THEN TURN THE POWER SWITCHES BACK ON. IF THE OSC LIGHT REMAINS EXTINGUISHED, TURN THE POWER SWITCHES TO OFF AND TAKE CORRECTIVE ACTION AS NECESSARY.

4.3.10 Set the appropriate DC Power Supply as follows:

2 Amp DC Power Supply #1 (Item 2.4)

METER switch to	A
V-A Range switch to	2A
V LIMIT control to	Mid-range
A LIMIT control to	Max (fully CW)
CURRENT LIMIT RANGE switch to	2A
Decade Dial switches to	0.00000
Power switch to	ON

10 Amp DC Power Supply #2 (Item 2.5)

VOLTAGE coarse and fine controls to	fully CCW
CURRENT coarse and fine controls to	fully CCW
LINE power switch to	ON

4.3.11. Adjust the TI's LOW TRACK control for a null indication on the NULL meter.

4.3.12 Adjust the Resistance Bridge COMP BAL (side panel) control for a null indication on the AMPERE TURN BALANCE meter.

CAUTION

DO NOT EXCEED THE TI INPUT CURRENT LIMITS.

RATIO 1000 terminal = 100 Amp
RATIO 100 terminal = 10 Amp
RATIO 10 terminal = 1 Amp

4.3.13 Adjust the DC Power Supply output controls to approximately 10% of the selected current.

4.3.14 Adjust the Resistance Bridge HIGH TRACK control to minimize the deflections on the AMPERE TURN BALANCE meter, while reversing the current with the CURRENT REVERSING switch.

4.3.15 Adjust the TI HIGH TRACK control to minimize the deflections on its NULL meter, while reversing the current with the Resistance Bridge CURRENT REVERSING switch (as in Step 4.3.14).

4.3.16 Readjust the TI LOW TRACK control for a null indication on the NULL meter.

4.3.17 Set the Resistance Bridge PCA/OUT switch to PCA.

4.3.18 Set the Resistance Bridge MAN/AUTO switch to AUTO.

NOTE

Automatic current reversing to be used as a convenience. For higher accuracy (particularly at low resistance values) a slower rate is required, either use a slower automatic rate (REV/RATE switch, side panel) or use manual switching (CURRENT REVERSING switch, front panel).

4.3.19 Adjust the Resistance Bridge Rx/Rs dials for an approximate balance on the GALVANOMETER meter.

NOTE

Balance is attained when the GALVANOMETER meter indication does not change upon current reversal.

4.3.20 Adjust the Resistance Bridge GALV BALANCE control to center the GALVANOMETER meter, if necessary.

4.3.21 Adjust the DC Power Supply output controls to 100% of the selected current. If using DC Power Supply #2 note the DMM indication.

4.3.22 Readjust the HIGH TRACK controls on both the Resistance Bridge and TI until no change is observed on the AMPERE TURN BALANCE and NULL meter respectively, upon current reversal.

4.3.23 Adjust the Resistance Bridge GALV BALANCE control to where the GALVANOMETER meter deflects equally on each side of center scale upon current reversal to compensate for thermal emf's.

4.3.24 Adjust the Resistance Bridge TRANSIENT SUPPRESSION control to minimize the transient "kick" on the GALVANOMETER meter.

4.3.25 Readjust Resistance Bridge Rx/Rs dials for a balance indication on the GALVANOMETER meter.

4.3.26 Increase the Resistance Bridge GALVANOMETER SENSITIVITY switch setting by one (i.e., X1 to X2)...

4.3.27 Readjust the Resistance Bridge GALV BALANCE control, if necessary.

4.3.28 Readjust the Rx/Rs dials for a balance indication on the GALVANOMETER meter.

4.3.29 Repeat steps 4.3.26 through 4.3.28 for the GALVANOMETER SENSITIVITY switch up to the setting which yields the required measuring sensitivity (8th place).

NOTE

When measuring a 1:1 Rx/Rs ratio the required measuring sensitivity is attained when the 8th place resolution can be interpolated from the GALVANOMETER meter indication.

4.3.30 Set the Resistance Bridge GALVANOMETER D1/D2 switch to the D2.

4.3.31 Readjust the Resistance Bridge Rx/Rs dials for a final balance using the GALVANOMETER meter as a null detector.

NOTE

Final balance is achieved when the GALVANOMETER meter indication stops drifting.

NOTE

If the above balance was carried out in the automatic current reserving mode with the REV/RATE switch set to 8, it is recommended that balancing be repeated at a slower rate (16) or use manual switching, unless previous experience proves otherwise.

NOTE

When using manual current reversing allow enough time for the GALVANOMETER meter indication to settle down before reversing current.

4.3.32 Record the Resistance Bridge Rx/Rs dials indication on the appropriate Worksheet as READING 1.

4.3.33 Set the equipments controls (in sequence) as follows:

1. Resistance Bridge

GALVANOMETER SENSITIVITY switch to	X1
GALVANOMETER D1/D2 switch to	D1
MAN/AUTO switch to	MAN

2. DC Power Supply

#1 (2 Amp)

Decade Dial switches to	0.00000
POWER switch to	OFF

#2 (10 Amp)

CURRENT controls	fully CCW
VOLTAGE controls	fully CCW
LINE power switch to	OFF

3. TI:

ON/OFF switch to	OFF
------------------	-----

4. Resistance Bridge

PCA/OUT switch to	OUT
CURRENT IxmA switch to	0
Rx/Rs dials to	1.000000-1

4.3.34 Repeat steps 4.3.6 through 4.3.33 two more times, allowing time for the Standard Resistor(s) to cool (approximately 5 minutes) before

testing. Recording the values as READING 2 and 3 on the appropriate Worksheet.

4.3.35 Enter the Standard Resistor data and the measured values recorded on the appropriate Worksheet into the HP9816 Computer Program CALEXTENDR. (See Appendix A for instructions.)

4.3.36 Record the CALEXTENDR computed values on the appropriate Worksheet.

4.3.37 Proceed to Subsection 4.4, 4.5, 4.6, 4.7 and 4.8 as applicable.

4.4 10:1 RATIO TEST

4.4.1 Perform Subsection 4.3 using equipment, control positions and outputs listed below. Record the measured values on Worksheet no. 2 under 10:1 RATIO Test No. 1.

TI Terminal Connection	TI RATIO Switch Position	Rs	Rx	DC Power Supply	Current
1A/R10	10	10 Ω	1 Ω	#1	10 mA 10% 100 mA 100%

NOTE

Exchange the Rx Primary Standard Resistor for reading 1, 2, and 3 as indicated by Worksheet no. 2.

4.4.3 Disconnect the Standard Resistors from the test setup.

4.4.4 Perform Subsection 4.3 using the equipment, control positions and outputs listed below. Record the measured values on Worksheet no. 2 under 10:1 RATIO Test No. 2.

TI Terminal Connection	TI RATIO Switch Position	Rs	Rx	DC Power Supply	Current
1A/R10	10	1 Ω	0.1 Ω	#1	30 mA 10% 300 mA 100%

NOTE

Exchange the Rs Primary Standard Resistor for reading 1, 2, and 3 as indicated by Worksheet no. 2.

4.4.5 Record the CALEXTENDR computed RATIO average value on Worksheet no. 2 and verify it is within ± 0.5 ppm of nominal (10.00000).

4.4.6 Disconnect the Standard Resistors from the test setup.

4.5 0.1 OHM AND 0.01 OHM STANDARD RESISTOR CALIBRATION

NOTE

The 0.1 ohm and 0.01 ohm Standard Resistors are calibrated on the TI 10:1 Range to establish an uncertainty of 0.4 ppm. The Standard Resistors will be used when calibrating the 100:1 RATIO range.

NOTE

Due to the uncertainty requirements the 0.1 ohm Standard Resistor requires recalibration at 1 Amp (used in the 100:1 Ratio Tests) because self-heating effects may cause a change in value greater than 0.5 ppm from the value recorded in Subsection 4.1.

4.5.1 Perform Subsection 4.3 using the equipment, control positions and outputs listed below. Record the measured values on Worksheet no. 3 under 0.1 ohm and 0.01 ohm calibration.

TI Terminal Connection	TI RATIO Switch Position	Rs	Rx	DC Power Supply	Current
1A/R10	10	*1Ω	0.1Ω	#1	100 mA 10% 1 A 100%
		0.1Ω	0.01Ω	#1	100 mA 10% 1 A 100%

***NOTE**

Exchange the Rs Primary Standard Resistor for reading 1, 2, and 3 as indicated by Worksheet no. 3.

4.5.2 Disconnect the Standard Resistors from the test setup.

4.6 100:1 RATIO TEST

4.6.1 Perform Subsection 4.3 using the equipment, control positions, and outputs listed below. Record the measured values on Worksheet no. 4 under 100:1 RATIO Test No. 1.

TI Terminal Connection	TI RATIO Switch Position	Rs	Rx	DC Power Supply	Current
10A/R100	100	1 Ω	0.01 Ω	#1	100 mA 10% 1 A 100%

NOTE

Exchange the Rs Primary Standard Resistor for reading 1, 2, and 3 as indicated by Worksheet no. 4.

4.6.2 Disconnect the Standard Resistors.

4.6.3 Perform Subsection 4.3 using the equipment, control positions and outputs listed below. Record the measured values on Worksheet no. 4 under 100:1 RATIO Test No. 2.

TI Terminal Connection	TI RATIO Switch Position	Rs	Rx	DC Power Supply	Current
10A/R100	100	10 Ω	0.1 Ω	#1	100 mA 10% 1 A 100%

4.6.4 Record the CALEXTENDR computed RATIO average value on Worksheet no. 4 and verify it is within ± 0.5 ppm of nominal (100.0000).

4.6.5 Disconnect the Standard Resistors and DC Power Supply from the test setup.

4.7 0.01 OHM and 0.001 OHM STANDARD RESISTOR CALIBRATION

NOTE

The 0.01 ohm and 0.001 ohm Standard Resistors are calibrated on the TI 100:1 range to establish an uncertainty of 0.4 ppm. The Standard Resistors will be used when calibrating the 1000:1 RATIO range.

NOTE

Due to the uncertainty requirements the 0.01 ohm Standard Resistor requires recalibration at 10 Amps (used in the 1000:1 RATIO test) because self heating effects may cause a change in value greater than 0.5 ppm from the value recorded in Subsection 4.5.

NOTE

The 15 AMP Current Shunt (Item 2.11) and DMM (Item 2.12) are added to the test configuration to ensure DC Power Supply #2 (Item 2.5) current output is at the desired level and will be resettable when verifying the TI 1000:1 RATIO range.

4.7.1 Perform Subsection 4.3 using the equipment, control positions and outputs listed below. Setting the DC Power Supply #2 current output for the desired level, note the DMM indication. Record the measured values on Worksheet no. 5 under 0.01 ohm and 0.001 ohm calibration.

TI Terminal Connection	TI RATIO Switch Position	Rs	Rx	DC Power Supply	Current Current	DMM Ind.
10A/R100	100	0.1Ω	0.001Ω	#2	1 A 10%	.1 Vdc
					10 A 100%	1 Vdc
		*1Ω	0.01Ω	#2	1 A 10%	.1 Vdc
					10 A 100%	1 Vdc

*NOTE

Exchange the Rs Primary Standard Resistor for reading 1, 2, and 3 as indicated by Worksheet no. 5.

4.7.2 Disconnect the Standard Resistors and DC Power Supply from the test setup.

4.8 1000:1 RATIO TEST

4.8.1 Perform Subsection 4.3 using the equipment, control positions and outputs listed below. Setting DC Power Supply #2 current output (DMM indication) to the value noted in Subsection 4.7. Record the measured values on Work sheet no. 6 under 1000:1 RATIO Test No. 1.

TI Terminal Connection	TI RATIO Switch Position	Rs	Rx	DC Power Supply	Current Current	DMM Ind.
100A/R1000	1000	10 Ω	0.01 Ω	#2	1 A 10% 10 A 100%	.1 Vdc 1 Vdc

4.8.2 Disconnect the Standard Resistors from the test setup.

4.8.3 Perform Subsection 4.3 using the equipment, control positions and outputs listed below. Setting DC Power Supply #2 current output (DMM indication) to the value noted in Subsection 4.7. Record the measured values on Worksheet no. 6 under 1000:1 RATIO Test No. 2.

TI Terminal Connection	TI RATIO Switch Position	Rs	Rx	DC Power Supply	Current Current	DMM Ind.
100A/R1000	1000	1 Ω	0.001 Ω	#2	1 A 10% 10 A 100%	.1 Vdc 1 Vdc

NOTE

Exchange the Rs Primary Standard Resistor for each reading 1, 2, and 3 as indicated by Worksheet no. 6.

4.8.4 Record the CALEXTENDR computed RATIO average value on Worksheet no. 6 and verify it is within ± 1 ppm of nominal (1000.000).

4.8.5 Unless additional tests are to be performed, turn all the power to off or standby and disconnect the test setup.

LCP-WJL-024
WORKSHEET no.1

DATE: _____

0.1 STANDARD RESISTOR CALIBRATION		
Rs = 0.1	Rx = 1	Rx/Rs Dials
Model no. <u>4221</u> Serial no. _____	Model no. <u>4210</u> no.1 Serial no. <u>1631004</u>	Reading no. 1 _____
	Model no. <u>4210</u> no. 2 Serial no. <u>1630985</u>	Reading no. 2 _____
	Model no. <u>4210</u> no. 3 Serial no. <u>1616926</u>	Reading no. 3 _____
Computed Value _____ Uncertainty _____ ppm		

10 STANDARD RESISTOR CALIBRATION		
Rs = 1	Rx = 10	Rx/Rs Dials
Model no. <u>4210</u> no.1 Serial no. <u>1631004</u>	Model no. <u>4025</u> Serial no. _____	Reading no. 1 _____
Model no. <u>4210</u> no. 2 Serial no. <u>1630985</u>		Reading no. 2 _____
Model no. <u>4210</u> no. 3 Serial no. <u>1616926</u>		Reading no. 3 _____
Computed Value _____ Uncertainty _____ ppm		

LCP-WJL-024
WORKSHEET no. 2

DATE: _____

10 : 1 RATIO TEST NO. 1		
Rs = 10	Rx = 1	Rx/Rs Dials
Model no. <u>4025</u> Serial no. _____	Model no. <u>4210</u> no.1 Serial no. <u>1631004</u> Model no. <u>4210</u> no. 2 Serial no. <u>1630985</u> Model no. <u>4210</u> no. 3 Serial no. <u>1616926</u>	Reading no. 1 _____ Reading no. 2 _____ Reading no. 3 _____
Computed Value _____ Uncertainty _____ ppm		
Computed 10 : 1 RATIO _____		

10 : 1 RATIO TEST NO. 2		
Rs = 1	Rx = 0.1	Rx/Rs Dials
Model no. <u>4210</u> no.1 Serial no. <u>1631004</u> Model no. <u>4210</u> no. 2 Serial no. <u>1630985</u> Model no. <u>4210</u> no. 3 Serial no. <u>1616926</u>	Model no. <u>4221</u> Serial no. _____	Reading no. 1 _____ Reading no. 2 _____ Reading no. 3 _____
Computed Value _____ Uncertainty _____ ppm		
Computed 10 : 1 RATIO _____		

LCP-WJL-024
WORKSHEET no. 3

DATE: _____

0.1 STANDARD RESISTOR CALIBRATION		
$R_s = 1$	$R_x = 0.1$	R_x/R_s Dials
Model no. <u>4210</u> Serial no. <u>1631004</u>	Model no. <u>4221</u> Serial no. _____	Reading no. 1 _____
Model no. <u>4210</u> Serial no. <u>1630985</u>		Reading no. 2 _____
Model no. <u>4210</u> Serial no. <u>1616926</u>		Reading no. 3 _____
Computed Value _____ Uncertainty _____ ppm		

0.01 STANDARD RESISTOR CALIBRATION		
$R_s = 0.1$	$R_x = 0.01$	R_x/R_s Dials
Model no. <u>4221</u> Serial no. _____	Model no. <u>4222</u> Serial no. _____	Reading no. 1 _____
		Reading no. 2 _____
		Reading no. 3 _____
Computed Value _____ Uncertainty _____ ppm		

LCP-WJL-024
WORKSHEET no. 4

DATE: _____

100 : 1 RATIO TEST NO. 1		
Rs = 1	Rx = 0.01	Rx/Rs Dials
Model no. <u>4210</u> no. 1 Serial no. <u>1631004</u>	Model no. <u>4222</u> Serial no. _____	Reading no. 1 _____
Model no. <u>4210</u> no. 2 Serial no. <u>1630985</u>		Reading no. 2 _____
Model no. <u>4210</u> no. 3 Serial no. <u>1616926</u>		Reading no. 3 _____
Computed Value _____ Uncertainty _____ ppm		
Computed 100 : 1 RATIO _____		

100 : 1 RATIO TEST NO. 2		
Rs = 10	Rx = 0.1	Rx/Rs Dials
Model no. <u>4025</u> Serial no. _____	Model no. <u>4221</u> Serial no. _____	Reading no. 1 _____
		Reading no. 2 _____
		Reading no. 3 _____
Computed Value _____ Uncertainty _____ ppm		
Computed 100 : 1 RATIO _____		

LCP-WJL-024
WORKSHEET no. 5

DATE: _____

0.001 STANDARD RESISTOR CALIBRATION		
$R_s = 0.1$	$R_x = 0.001$	R_x/R_s Dials
Model no. <u>4221</u> Serial no. _____	Model no. <u>4223</u> Serial no. _____	Reading no. 1 _____ Reading no. 2 _____ Reading no. 3 _____
Computed Value _____ Uncertainty _____ ppm		

0.01 STANDARD RESISTOR CALIBRATION		
$R_s = 1$	$R_x = 0.01$	R_x/R_s Dials
Model no. <u>4210</u> Serial no. <u>1631004</u>	Model no. <u>4222</u> Serial no. _____	Reading no. 1 _____
Model no. <u>4210</u> Serial no. <u>1630985</u>		Reading no. 2 _____
Model no. <u>4210</u> Serial no. <u>1616926</u>		Reading no. 3 _____
Computed Value _____ Uncertainty _____ ppm		

LCP-WJL-024
WORKSHEET no. 6

DATE: _____

1000 : 1 RATIO TEST NO. 1		
Rs = 10	Rx = 0.01	Rx/Rs Dials
Model no. <u>4025</u> Serial no. _____	Model no. <u>4222</u> Serial no. _____	Reading no. 1 _____ Reading no. 2 _____ Reading no. 3 _____
Computed Value _____ Uncertainty _____ ppm		
Computed 1000 : 1 RATIO _____		

1000 : 1 RATIO TEST NO. 2		
Rs = 1	Rx = 0.001	Rx/Rs Dials
Model no. <u>4210</u> no. 1 Serial no. <u>1631004</u>	Model no. <u>4223</u> Serial no. _____	Reading no. 1 _____
Model no. <u>4210</u> no. 2 Serial no. <u>1630985</u>		Reading no. 2 _____
Model no. <u>4210</u> no. 3 Serial no. <u>1616926</u>		Reading no. 3 _____
Computed Value _____ Uncertainty _____ ppm		
Computed 1000 : 1 RATIO _____		

APPENDIX A
CALEXTENDR PROGRAM INSTRUCTIONS

A.1 CALEXTENDR PRELIMINARY PREPARATION

A.1.1 Load CALEXTENDR program into the HP 9816 computer.

A.1.2 Press RUN.

A.1.3 Enter Date: Year/Month/Day

A.1.4 CALEXTENDR will load the Standard Resistor historical values as recorded by MCP-WJL-002 into data files for comparison and verification of measured values.

A.1.5 CALEXTENDR will display Calibration Menu:

Subsection

4.1	0.1 & 10 Ohm Calibration
4.4	10:1 RATIO Test
4.5	0.1 & 0.01 Ohm Calibration
4.6	100:1 RATIO Test
4.7	0.01 & 0.001 Ohm Calibration
4.8	1000:1 RATIO Test

A.1.6 Select the Subsection Calibration being performed.

NOTE

The Subsection calculations must be performed in sequence to ensure valid results.

A.2 STANDARD RESISTOR CALCULATIONS

NOTE

These calculations will be performed for Subsection 4.1, 4.5, and 4.7.

A.2.1 Enter the serial number of the Standard Resistor being measured.

A.2.2 CALEXTENDR will verify the correct serial number was entered. If the serial number is incorrect, CALEXTENDR will request that it be re-entered or the procedure be restarted.

A.2.3 Enter READING 1, 2 and 3.

A.2.4 CALEXTENDR will display the values entered and ask if they are correct. If incorrect, the values may be re-entered.

A.2.5 CALEXTENDR will calculate the Standard Resistor's value and standard deviation.

NOTE

When the Standard Resistor is measured utilizing the TI, the measured RATIO value will be figured into the calculations.

A.2.6 CALEXTENDR will determine whether the value is in tolerance or not. If out of tolerance, CALEXTENDR will request the READINGS to be re-checked/re-entered or be re-measured.

A.2.7 CALEXTENDR will store and print the Standard Resistors:

Serial no.

MCP Value:

Ref. Value: (to be used in RATIO tests)

Standard Deviation:

A.2.8 Record the values on the Worksheet.

A.2.9 Repeat steps A.2.1 through A.2.8 for the second Standard Resistor's calculation.

A.2.10 CALEXTENDR will return to Calibration Menu.

A.2.11 Proceed with the next subsection calibration.

A.3 RATIO TEST CALCULATIONS

NOTE

These calculations will be performed for Subsection 4.4, 4.6 and 4.8.

A.3.1 Enter the serial number of the Standard Resistor being measured.

A.3.2 CALEXTENDR will verify the correct serial number was entered. If the serial number is incorrect, CALEXTENDR will request that it be re-entered or the procedure be restarted.

A.3.3 Enter READING 1, 2 and 3.

A.3.4 CALEXTENDR will display the values entered and ask if they are correct. If incorrect, the values may be re-entered.

A.3.5 CALEXTENDR will calculate the Standard Resistor's value, standard deviation and the TI's RATIO value.

A.3.6 CALEXTENDR will determine whether the values are within tolerance or not. If out of tolerance, CALEXTENDR will request the READINGS to be rechecked/re-entered or be remeasured.

NOTE

The Standard Resistor value is compared to the value determined in the previous Standard Resistor calibration to determine the TI RATIO value.

A.3.7 CALEXTENDR will store and print:

Serial no.

Ref. Value: (measured in Standard Resistor Calibration)

Measured Value: (measured in RATIO test)

Standard Deviation:

RATIO Value:

A.3.8 Record the values on the Worksheet.

A.3.9 Repeat Steps A.3.1 through A.3.8 for the second RATIO test.

A.3.10 CALEXTENDR will calculate and print the average RATIO value.

A.3.11 Record the average RATIO value on the Worksheet.

A.3.12 CALEXTENDR will return to the Calibration Menu.

A.3.13 Proceed with next Subsection calibration.

```

10 | PROGRAM: CALEXTENDR
20 | WRITTEN 12/17/86 BY JOE
30 | PROGRAM TO CALCULATE VALUES FOR STANDARD RESISTORS
40 | BEING USED TO CALIBRATE THE RANGE EXTENDER AND CALCULATE
50 | THE RATIOS OF THE EXTENDER
60 | OPTION BASE 1
70 | COM @Standard,@Memory
80 | COM Values(60,6),L1(60),Std(3,4),Valu(15,2),W(12),Y(3),St(3),R1,R2,R3,Sd,U
  | (3),Ratio10,Ratio100
90 | ASSIGN @Memory TO "Stdresist"
100 | FOR I=1 TO 60
110 |     FOR J=1 TO 6
120 |         ENTER @Memory;Values(I,J)
130 |     NEXT J
140 | NEXT I
150 | FOR I=1 TO 60
160 |     IF Values(I,1)=0 THEN 190
170 |     Q=I
180 |     L1(I)=Values(I,4)
190 | NEXT I
200 | FOR I=1 TO Q
210 |     Lr1=Lr1+L1(I)
220 | NEXT I
230 | Lr1=Lr1/Q
240 | ASSIGN @Standard TO "Std"
250 | FOR I=1 TO 3
260 |     FOR J=1 TO 4
270 |         ENTER @Standard;Std(I,J)
280 |     NEXT J
290 | NEXT I
300 | FOR I=1 TO 3
310 |     U(I)=Std(I,1)
320 | NEXT I
330 | M=(U(1)+U(2)+U(3))/3
340 | ASSIGN @Memory TO "Valu"
350 | FOR I=1 TO 15
360 |     FOR J=1 TO 2
370 |         ENTER @Memory;Valu(I,J)
380 |     NEXT J
390 | NEXT I
400 | Z=0
410 | PRINT "ENTER 1 IF YOU ARE AT 4.1 0.1 & 10 OHM CALIBRATION"
420 | PRINT "ENTER 2 IF YOU ARE AT 4.4 10:1 RATIO TEST"
430 | PRINT "ENTER 3 IF YOU ARE AT 4.5 0.1 & 0.01 OHM CALIBRATION"
440 | PRINT "ENTER 4 IF YOU ARE AT 4.6 100:1 RATIO TEST"
450 | PRINT "ENTER 5 IF YOU ARE AT 4.7 0.01 & 0.001 OHM CALIBRATION"
460 | PRINT "ENTER 6 IF YOU ARE AT 4.8 1000:1 RATIO TEST"
470 | INPUT Z
480 | IF Z=1 THEN 550
490 | IF Z=2 THEN 1160
500 | IF Z=3 THEN 1880
510 | IF Z=4 THEN 2400
520 | IF Z=5 THEN 3110
530 | IF Z=6 THEN 3630
540 | GOTO 400
550 | INPUT "ENTER FROM KEYBOARD TODAYS DATE (YYMMDD)",Date
560 | INPUT "WHAT SERIAL NUMBER FOR 0.1 OHM RESISTOR ?",B
570 | IF B<>Valu(3,2) THEN 590
580 | GOTO 620
590 | PRINT "ERROR IN DATA PLEASE RE-ENTER OR START OVER !!!"

```

```

600 BEEP 1000,1
610 GOTO 560
620 FOR I=1 TO 12
630 W(I)=0
640 NEXT I
650 GOSUB Enterdata
660 R1=V(1)/Y(1)
670 R2=V(2)/Y(2)
680 R3=V(3)/Y(3)
690 Res=(R1+R2+R3)/3
700 W(1)=PROUND(Res,-9)
710 St1=V(1)/W(1)
720 St2=V(2)/W(1)
730 St3=V(3)/W(1)
740 GOSUB Compsd
750 PRINTER IS 706
760 IF PROUND(W(1)-Valu(3,1)*10,-8)>2.E-7 THEN 780
770 GOTO 800
780 PRINT "DIFFERENCE IS ";PROUND(W(1)-Valu(3,1),-9)*1.E+7;"PPM"
790 GOTO 4330
800 PRINT USING 820;Valu(3,2),Valu(3,1),W(1),PROUND(Sd*1.E+5,-3)
810 PRINT
820 IMAGE "SERIAL NUMBER : ",7D,L,"MCP VALUE : ",Z.11D,L,"REF. VALUE : ",Z.11D
,L,"STANDARD DEVIATION : ",1Z.3D
830 IMAGE "SERIAL NUMBER : ",7D,L,"NEW REF. VALUE : ",Z.11D,L,"STANDARD DEVIAT
ION : ",1Z.3D
840 IMAGE "SERIAL NUMBER : ",7D,L,"REF. VALUE : ",Z.11D,L,"MEASURED VALUE : ",
Z.11D,L,"STANDARD DEVIATION : ",1Z.3D
850 IMAGE "SERIAL NUMBER : ",7D,L,"MCP VALUE : ",Z.2.8D,L,"REF. VALUE : ",Z.2.8D
,L,"STANDARD DEVIATION : ",1Z.3D
860 IMAGE "SERIAL NUMBER : ",7D,L,"REF. VALUE : ",Z.2.8D,L,"MEASURED VALUE : ",
Z.2.8D,L,"STANDARD DEVIATION : ",1Z.3D
870 PRINTER IS 1
880 INPUT "WHAT SERIAL NUMBER FOR 10 OHM RESISTOR ? ",B
890 IF B<>Valu(5,2) THEN 910
900 GOTO 940
910 PRINT "ERROR IN DATA PLEASE RE-ENTER OR START OVER !!!"
920 BEEP 1000,1
930 GOTO 880
940 GOSUB Enterdata
950 GOSUB Stdissr
960 Res=(R1+R2+R3)/3
970 W(2)=PROUND(Res,-7)
980 St1=W(2)/V(1)
990 St2=W(2)/V(2)
1000 St3=W(2)/V(3)
1010 GOSUB Compsd
1020 PRINTER IS 706
1030 IF PROUND((W(2)-Valu(5,1))/10,-8)>2.E-7 THEN 1050
1040 GOTO 1070
1050 PRINT "DIFFERENCE IS ";PROUND(W(2)-Valu(5,1),-7)*1.E+5;"PPM"
1060 GOTO 4330
1070 PRINT USING 850;Valu(5,2),Valu(5,1),W(2),PROUND(Sd*1.E+5,-3)
1080 PRINT
1090 PRINTER IS 1
1100 PRINT "TIME TO MAKE NEXT SERIES OF MEASUREMENTS ."
1110 ASSIGN @Memory TO "HOLDDATA"
1120 FOR I=1 TO 12
1130 OUTPUT @Memory;W(I)
1140 NEXT I

```

```

1150 GOTO 4640
1160 ASSIGN @Memory TO "HOLDDATA"
1170 FOR I=1 TO 12
1180   ENTER @Memory;W(I)
1190 NEXT I
1200 INPUT "WHAT SERIAL NUMBER FOR 10 OHM RESISTOR ?",B
1210 IF B<>Valu(5,2) THEN 1230
1220 GOTO 1260
1230 PRINT "ERROR IN DATA PLEASE RE-ENTER OR START OVER !!!"
1240 BEEP 1000,1
1250 GOTO 1200
1260 GOSUB Enterdata
1270 R1=(V(1)*10)/Y(1)
1280 R2=(V(2)*10)/Y(2)
1290 R3=(V(3)*10)/Y(3)
1300 Res=(R1+R2+R3)/3
1310 W(3)=PROUND(Res,-7)
1320 St1=(V(1)*10)/W(3)
1330 St2=(V(2)*10)/W(3)
1340 St3=(V(3)*10)/W(3)
1350 GOSUB Compsd
1360 PRINTER IS 706
1370 IF PROUND((W(3)-W(2))/10,-8)>5.E-7 THEN 1390
1380 GOTO 1410
1390 PRINT PROUND(W(3)-W(2),-7)*1.E+5;"PPM"
1400 GOTO 4330
1410 PRINT USING 860;Valu(5,2),W(2),W(3),PROUND(Sd*1.E+6,-3)
1420 Ratio1=10.0000000+PROUND(((W(2)-W(3))),-7)
1430 PRINT
1440 PRINT "RATIO IS :";PROUND(Ratio1,-7)
1450 PRINT
1460 PRINTER IS 1
1470 INPUT "WHAT SERIAL NUMBER FOR 0.1 OHM RESISTOR ?",B
1480 IF B<>Valu(3,2) THEN 1500
1490 GOTO 1530
1500 PRINT "ERROR IN DATA PLEASE RE-ENTER OR START OVER !!!"
1510 BEEP 1000,1
1520 GOTO 1470
1530 GOSUB Enterdata
1540 GOSUB Stdisrs
1550 Res=(R1+R2+R3)/3
1560 W(4)=PROUND(Res/10,-9)
1570 St1=W(4)*10/V(1)
1580 St2=W(4)*10/V(2)
1590 St3=W(4)*10/V(3)
1600 GOSUB Compsd
1610 PRINTER IS 706
1620 IF PROUND((W(4)-W(1))*10,-8)>3.E-7 THEN 1640
1630 GOTO 1660
1640 PRINT PROUND(W(4)-W(1),-9)*1.E+7;"PPM"
1650 GOTO 4330
1660 PRINT USING 840;Valu(3,2),W(1),W(4),PROUND(Sd*1.E+6,-3)
1670 PRINT
1680 Ratio2=10.0000000+PROUND(((W(1)-W(4))*100),-7)
1690 PRINT "RATIO IS :";PROUND(Ratio2,-7)
1700 PRINT
1710 PRINT
1720 IF PROUND(Ratio1-Ratio2,-8)*1.E+6<-5 OR PROUND(Ratio1-Ratio2,-8)*1.E+6>5 T
HEN 1770
1730 Ratio10=PROUND((Ratio1+Ratio2)/2,-7)

```

```

1740 PRINT "RATIO OF TIMES 10 RANGE IS :";PROUND(Ratio10,-7)
1750 PRINT
1760 GOTO 1810
1770 PRINT "RATIO IS OUT OF TOLERANCE !! RATIO IS :";PROUND((Ratio1+Ratio2)/2
,-7)
1780 PRINT "RE-MEASURE THEN TRY AGAIN !!"
1790 PRINTER IS 1
1800 GOTO 4640
1810 PRINTER IS 1
1820 PRINT "TIME TO MAKE NEXT SERIES OF MEASUREMENTS ."
1830 ASSIGN @Memory TO "HOLDDATA"
1840 FOR I=1 TO 12
1850 OUTPUT @Memory;W(I)
1860 NEXT I
1870 GOTO 4640
1880 ASSIGN @Memory TO "HOLDDATA"
1890 FOR I=1 TO 12
1900 ENTER @Memory;W(I)
1910 NEXT I
1920 INPUT "WHAT SERIAL NUMBER FOR 0.1 OHM RESISTOR ?",B
1930 IF B<>Valu(3,2) THEN 1950
1940 GOTO 1980
1950 PRINT "ERROR IN DATA PLEASE RE-ENTER OR START OVER !!!"
1960 BEEP 1000,1
1970 GOTO 1920
1980 GOSUB Enterdata
1990 GOSUB Stdists
2000 Res=(R1+R2+R3)/3
2010 W(5)=PROUND(Res/10,-9)
2020 St1=W(5)/V(1)*10
2030 St2=W(5)/V(2)*10
2040 St3=W(5)/V(3)*10
2050 GOSUB Compsd
2060 PRINTER IS 706
2070 PRINT USING 830;Valu(3,2),W(5),PROUND(Sd*1.E+6,-3)
2080 PRINT
2090 PRINTER IS 1
2100 INPUT "WHAT SERIAL NUMBER FOR 0.01 OHM RESISTOR ?",B
2110 IF B<>Valu(2,2) THEN 2130
2120 GOTO 2160
2130 PRINT "ERROR IN DATA PLEASE RE-ENTER OR START OVER !!!"
2140 BEEP 1000,1
2150 GOTO 2100
2160 GOSUB Enterdata
2170 R1=Y(1)*W(1)
2180 R2=Y(2)*W(1)
2190 R3=Y(3)*W(1)
2200 Res=(R1+R2+R3)/3
2210 W(6)=PROUND(Res/10,-10)
2220 St1=W(6)/W(1)*10
2230 St2=W(6)/W(1)*10
2240 St3=W(6)/W(1)*10
2250 GOSUB Compsd
2260 PRINTER IS 706
2270 IF ABS(PROUND((W(6)-Valu(2,1))*100,-8))>5.E-7 THEN 2290
2280 GOTO 2310
2290 PRINT "DIFFERENCE IS ";PROUND((W(6)-Valu(2,1))*100,-8)*1.E+6;"PPM"
2300 GOTO 4330
2310 PRINT USING 820;Valu(2,2),Valu(2,1),W(6),PROUND(Sd*1.E+6,-3)
2320 PRINT

```

```

2330 PRINTER IS 1
2340 PRINT "TIME TO MAKE NEXT SERIES OF MEASUREMENTS ."
2350 ASSIGN @Memory TO "HOLDDATA"
2360 FOR I=1 TO 12
2370     OUTPUT @Memory;W(I)
2380 NEXT I
2390 GOTO 4640
2400 ASSIGN @Memory TO "HOLDDATA"
2410 FOR I=1 TO 12
2420     ENTER @Memory;W(I)
2430 NEXT I
2440 INPUT "WHAT SERIAL NUMBER FOR 0.01 OHM RESISTOR ?",B
2450 IF B<>Valu(2,2) THEN 2470
2460 GOTO 2500
2470 PRINT "ERROR IN DATA PLEASE RE-ENTER OR START OVER !!!"
2480 BEEP 1000,1
2490 GOTO 2440
2500 GOSUB Enterdata
2510 GOSUB Stdists
2520 Res=(R1+R2+R3)/3
2530 W(7)=PROUND(Res/100,-10)
2540 St1=W(7)*100/V(1)
2550 St2=W(7)*100/V(2)
2560 St3=W(7)*100/V(3)
2570 GOSUB Compsd
2580 PRINTER IS 706
2590 IF ABS(PROUND((W(7)-W(6))*100,-8))>5.E-7 THEN 2610
2600 GOTO 2630
2610 PRINT "DIFFERENCE IS ";PROUND((W(7)-W(6))*100,-8)*1.E+6;"PPM"
2620 GOTO 4330
2630 PRINT USING 840;Valu(2,2),W(6),W(7),PROUND(Sd*1.E+5,-3)
2640 PRINT
2650 Ratio1=100.000000+PROUND(((W(7)-W(6))*1.E+4),-6)
2660 PRINT "RATIO IS :";PROUND(Ratio1,-6)
2670 PRINT
2680 PRINTER IS 1
2690 INPUT "WHAT SERIAL NUMBER FOR 0.1 OHM RESISTOR ?",B
2700 IF B<>Valu(3,2) THEN 2720
2710 GOTO 2750
2720 PRINT "ERROR IN DATA PLEASE RE-ENTER OR START OVER !!!"
2730 BEEP 1000,1
2740 GOTO 2690
2750 GOSUB Enterdata
2760 R1=Y(1)*W(2)
2770 R2=Y(2)*W(2)
2780 R3=Y(3)*W(2)
2790 Res=(R1+R2+R3)/3
2800 W(8)=PROUND(Res/100,-9)
2810 St1=W(8)*100/W(2)
2820 St2=St1
2830 St3=St1
2840 GOSUB Compsd
2850 PRINTER IS 706
2860 IF PROUND(W(8)-W(5)*10,-8)>5.E-6 THEN 2880
2870 GOTO 2900
2880 PRINT "DIFFERENCE IS ";PROUND(W(8)-W(5)*10,-8)*1.E-6;"PPM"
2890 GOTO 4330
2900 PRINT USING 840;Valu(3,2),W(5),W(8),PROUND(Sd*1.E+5,-3)
2910 PRINT
2920 Ratio2=100.000000+PROUND((W(5)-W(8))*1.E+4,-6)

```

```

2930 PRINT "RATIO IS :";PROUND(Ratio2,-6)
2940 PRINT
2950 PRINT
2960 IF PROUND(Ratio1-Ratio2,-5)*1.E+5<-5 OR PROUND(Ratio1-Ratio2,-5)*1.E+5>5 T
HEN 3010
2970 Ratio100=PROUND((Ratio1+Ratio2)/2,-6)
2980 PRINT
2990 PRINT "RATIO OF TIMES 100 RANGE IS :";PROUND(Ratio100,-6)
3000 GOTO 3040
3010 PRINT "RATIO IS OUT OF TOLERANCE !!    RATIO IS :";PROUND((Ratio1-Ratio2)/2
,-5)
3020 PRINT "RE-MEASURE THEN TRY AGAIN !!"
3030 GOTO 4640
3040 PRINTER IS 1
3050 PRINT "TIME TO MAKE NEXT SERIES OF MEASUREMENTS ."
3060 ASSIGN @Memory TO "HOLDDATA"
3070 FOR I=1 TO 12
3080     OUTPUT @Memory;W(I)
3090 NEXT I
3100 GOTO 4640
3110 ASSIGN @Memory TO "HOLDDATA"
3120 FOR I=1 TO 12
3130     ENTER @Memory;W(I)
3140 NEXT I
3150 INPUT "WHAT SERIAL NUMBER FOR 0.001 OHM RESISTOR ?";B
3160 IF B<>Valu(1,2) THEN 3180
3170 GOTO 3210
3180 PRINT "ERROR IN DATA PLEASE RE-ENTER OR START OVER !!!"
3190 BEEP 1000,1
3200 GOTO 3150
3210 GOSUB Enterdata
3220 R1=Y(1)*W(1)
3230 R2=Y(2)*W(1)
3240 R3=Y(3)*W(1)
3250 Res=(R1+R2+R3)/3
3260 W(9)=PROUND(Res/100,-11)
3270 St1=W(9)*100/W(1)
3280 St2=St1
3290 St3=St1
3300 GOSUB Compsd
3310 PRINTER IS 706
3320 IF ABS(PROUND((W(9)-Valu(1,1))*1000,-8))>5.E-7 THEN 3340
3330 GOTO 3360
3340 PRINT "DIFFERENCE IS ";PROUND(W(9)-Valu(1,1)*1000,-3)*1.E+6;"PPM"
3350 GOTO 4330
3360 PRINT USING 820;Valu(1,2),Valu(1,1),W(9),PROUND(Sd*1.E+6,-3)
3370 PRINT
3380 PRINTER IS 1
3390 INPUT "WHAT SERIAL NUMBER FOR 0.01 OHM RESISTOR ?";B
3400 IF B<>Valu(2,2) THEN 3420
3410 GOTO 3450
3420 PRINT "ERROR IN DATA PLEASE RE-ENTER OR START OVER !!!"
3430 BEEP 1000,1
3440 GOTO 3390
3450 GOSUB Enterdata
3460 GOSUB Stdists
3470 Res=(R1+R2+R3)/3
3480 W(10)=PROUND(Res/100,-10)
3490 St1=W(10)*100/V(1)
3500 St2=W(10)*100/V(2)

```

```

3510 St3=W(10)*100/V(3)
3520 GOSUB Compsd
3530 PRINTER IS 706
3540 PRINT USING 830;Valu(2,2),W(10),PROUND(Sd*1.E+6,-3)
3550 PRINT
3560 PRINTER IS 1
3570 PRINT "TIME TO MAKE NEXT SERIES OF MEASUREMENTS ."
3580 ASSIGN @Memory TO "HOLDDATA"
3590 FOR I=1 TO 12
3600     OUTPUT @Memory;W(I)
3610 NEXT I
3620 GOTO 4640
3630 ASSIGN @Memory TO "HOLDDATA"
3640 FOR I=1 TO 12
3650     ENTER @Memory;W(I)
3660 NEXT I
3670 INPUT "WHAT SERIAL NUMBER FOR 0.01 OHM RESISTOR ?",B
3680 IF B<>Valu(2,2) THEN 3700
3690 GOTO 3730
3700 PRINT "ERROR IN DATA PLEASE RE-ENTER OR START OVER !!!"
3710 BEEP 1000,1
3720 GOTO 3670
3730 GOSUB Enterdata
3740 R1=Y(1)*W(2)
3750 R2=Y(2)*W(2)
3760 R3=Y(3)*W(2)
3770 Res=(R1+R2+R3)/3
3780 W(11)=PROUND(Res/1000,-10)
3790 St1=W(11)*1000/W(2)
3800 St2=St1
3810 St3=St1
3820 GOSUB Compsd
3830 PRINTER IS 706
3840 IF ABS(PROUND((W(11)-W(10))*100,-8))>1.E-6 THEN 3860
3850 GOTO 3880
3860 PRINT "DIFFERENCE IS ";PROUND((W(11)-W(10))*100,-8)*1.E+6;"PPM"
3870 GOTO 4330
3880 PRINT USING 840;Valu(2,2),W(10),W(11),PROUND(Sd*1.E+6,-3)
3890 PRINT
3900 Ratio1=1000.00000+PROUND((W(11)-W(10))*1.E+5,-5)
3910 PRINT "RATIO IS :";PROUND(Ratio1,-5)
3920 PRINT
3930 PRINTER IS 1
3940 INPUT "WHAT SERIAL NUMBER FOR 0.001 OHM RESISTOR ?",B
3950 IF B<>Valu(1,2) THEN 3970
3960 GOTO 4000
3970 PRINT "ERROR IN DATA PLEASE RE-ENTER OR START OVER !!!"
3980 BEEP 1000,1
3990 GOTO 3940
4000 GOSUB Enterdata
4010 GOSUB Stdists
4020 Res=(R1+R2+R3)/3
4030 W(12)=PROUND(Res/1000,-11)
4040 St1=W(12)*1000/V(1)
4050 St2=W(12)*1000/V(2)
4060 St3=W(12)*1000/V(3)
4070 GOSUB Compsd
4080 PRINTER IS 706
4090 IF ABS(PROUND((W(12)-W(9))*1000,-8))>5.E-6 THEN 4110
4100 GOTO 4130

```

```

4110 PRINT "DIFFERENCE IS ";PROUND(W(11)-W(9)*1000,-7)*1.E+6;"PPM"
4120 GOTO 4330
4130 PRINT USING 840;Valu(1,2),W(9),W(12),PROUND(Sd*1.E+6,-3)
4140 PRINT
4150 Ratio2=1000.00000+PROUND((W(12)-W(9))*1.E+6,-5)
4160 PRINT "RATIO IS :";PROUND(Ratio2,-5)
4170 PRINT
4180 PRINT
4190 IF PROUND(Ratio1-Ratio2,-4)*1.E+3<-1 OR PROUND(Ratio1-Ratio2,-4)*1.E+3>1 T
HEN 4230
4200 PRINT "RATIO OF TIMES 1000 RANGE IS :";(Ratio1+Ratio2)/2
4210 OUTPUT 706;"

```

```

4220 GOTO 4260
4230 PRINT "RATIO IS OUT OF TOLERANCE !!  RATIO IS :";(Ratio1-Ratio2)/2
4240 PRINT "RE-MEASURE THEN TRY AGAIN !!"
4250 GOTO 4640
4260 PRINTER IS 1
4270 PRINT "FINISHED !!!!!!!!!!!!!!"
4280 ASSIGN @Memory TO "HOLDDATA"
4290 FOR I=1 TO 12
4300     OUTPUT @Memory;W(I)
4310 NEXT I
4320 GOTO 4640
4330 PRINTER IS 706
4340 PRINT "DIFFERENCE IS TOO LARGE !!!!!"
4350 PRINT
4360 PRINT "CHECK YOUR VALUES AND EITHER RE-MEASURE OR RE-ENTER !!"
4370 PRINT "YOU MUST RE-START PROGRAM !!!!!"
4380 GOTO 4640
4390 Enterdata: !SUB
4400 FOR U=1 TO 3
4410     PRINT "ENTER ON KEYBOARD OBSERVATION",U
4420     INPUT Y(U)
4430 NEXT U
4440 A$=""
4450 PRINT "YOU HAVE ENTERED THIS DATA :"
4460 FOR U=1 TO 3
4470     PRINT Y(U)
4480 NEXT U
4490 PRINT "IS IT CORRECT ? (ENTER 'N' OR CONT)"
4500 INPUT A$
4510 IF A$="N" THEN 4400
4520 RETURN
4530 Stdissrs: !SUB
4540 R1=Y(1)*U(1)
4550 R2=Y(2)*U(2)
4560 R3=Y(3)*U(3)
4570 RETURN
4580 Compsd: !SUB
4590 S1=Y(1)-St1
4600 S2=Y(2)-St2
4610 S3=Y(3)-St3
4620 Sd=SQR(S1^2+S2^2+S3^2)
4630 RETURN
4640 PRINTER IS 1
4650 END

```