

ThermoPro TP50 Temperature and Humidity Monitor



TP50 Specification

Temperature Range	-22.0 to 140.0°F(-30.0 to 60.0°C)
Temperature Tolerance	±1°F(±0.5°C)from 32 to 140°F(0 to 60°C) otherwise ±1.8°F(±1°C)
Humidity Range	10%~99%
Humidity Tolerance	±2%from 30% to 80%, otherwise ±3%
Sensor Type	NTC
Refresh Rate	10 seconds
Display	LCD, 2 1/8 Length x 1 3/4 Width inches(54.0L x45.0W mm)
Backlight	N
Unit Size	3 1/8 Length x 2 5/8 Width x 1 Height inches (79.0L x 66.0W x24.0H mm)
Power	1.5V (1xAAA Battery)