


BK PRECISION 369B ADJUSTMENT LOCATIONS



Remove battery cover, then remove three screws from the back cover.

Carefully lift front panel (includes main circuit board). Do not pull on ribbon cable, as it is very fragile.

Set T.I. for 400 Amp DC range and adjust for zero reading with no current applied.

Adjust others as needed with a near full range input.