

HP 4062UX Semiconductor Process Control System
HP 4062F Semiconductor Parametric Test System

Read Me Before Installing
HP 4062UX/F System Software
Revision 8.00



HP Part No. 04062-90917
Printed in Japan October 1998

Edition 1
E1098

Read Me Before Installing HP 4062UX/F System Software Revision 8.00

Introduction

This document is for system administrators and service personnel of the HP 4062UX Semiconductor Process Control System and the HP 4062F Semiconductor Parametric Test System. Read this document before installing or updating software.

This document covers changes that are included in revision 8.00 of the system software. New features and notations to install, update, and use the software are described.

“New Features” introduces the major new features included in revision 8.00. This section is for system administrators.

“Before Installing the System Software” describes notations for the HP 4062UX/F installation. It is supplemental but important information for the HP 4062UX/F *Installation Manual*. This section is for system administrators and service personnel.

New Features

Year 2000 Compliant.

HP 4062UX/F system software revision 8.00 or later complies with Year 2000 issue.

New Prober Control Subprogram Library.

Prober control subprogram library TSK90A is newly included in HP 4062UX/F system software revision 8.00 or later.

TSK90A supports Tokyo Seimitsu A-PM 90A and UF200 probers.

Before Installing the System Software

This section provides supplemental information when you install or update the HP 4062UX/F system software.

Note



When installing the HP 4062UX/F system software with the HP IMA software, you must install the HP 4062UX/F system software first, then install the HP IMA software.

If you install the HP IMA software first, then install the HP 4062UX/F system software, the HP 4062UX/F system will not start up properly.

Software Compatibility

Before you install or update the software, make sure that the HP BASIC/UX and the HP-UX software revisions are compatible with the HP 4062UX/F revision.

The following table shows correspondence at the operating system with the HP 4062UX/F system software and the HP Interactive Measurement and Analysis (IMA) software. The checked (✓) rows is for revision 7.11.

Software Revisions for the HP 4062UX/F(HP 9000 Series 700 Model)

	HP 4062UX/F Software Revision	HP IMA Software Revision	HP-UX System Revision	HP BASIC/UX Revision
	X.07.00 F.07.00	B.02.30	9.05	7.01 with HP SICL 3.01 or later
	X.07.10 F.07.10	B.02.40	9.05	7.1
	X.07.11 F.07.11	B.02.41	9.05	7.11
✓	X.08.00 F.08.00	B.02.50	10.20 ¹	8.02 with HP SICL E.01.01

¹ Additional Core Enhancements(ACE)3, other patches for Year 2000, and Software Configuration Tools are required. Refer to *HP 4062UX/F Upgrade Guide* for more detail information.